1001 D St. (Commercial Building) (Carpel's Liquor Store; Fotomat) Washington District of Columbia HABS No. DC-488 HABS
DC,
WASH,

### **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

United States Department of the Interior Heritage Conservation and Recreation Service Washington, D.C. 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY

ARCHITECTURAL DATA FORM

		•		at 40-
STATE Disamina of Columbia	COUNTY		TOWN OR VICI	NITY
District of Columbia			Washington	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.
1001 D. St. (Commercial Building)				DC-488
SECONOARY OR COMMON NAMES	OF STRUCTURE			
Carpel's Liquor Store/Fot	omat			
COURT ACRES (PECCOLS	F 1004710U F05	DUDAL CITEC		
COMPLETE AODRESS (DESCRIB 1001 D Street, N.W., Wash				
Tool D octeet, M.W., Wash	ington, D.C.,	square 546, 12	ot 800.	
DATE OF CONSTRUCTION (INC	LUDE SOURCE)	ARCHITECT(S)	(INCLUDE SOURCE)	
c. 1853 (see attached)		unknown		
SIGNIFICANCE (ARCHITECTUR	AL AND HISTORI	CAL INCLUDE	ORIGINAL USE OF ST	RUCTURE
This handsome 19th Century	AL AND HISTORY V commercial by	uilding effect	ively anchore the	corner of Tenth and
D Streets. It is an inter	gral element in	a row of bui	ldings whose strong	cohesive characte
is derived from similarit	ies in proporti	lons. The buil	ding is located in	the Pennsylvania
Avenue Historic District.				
STYLE (IF APPROPRIATE) Altered Federal (Comm	ercial)			
MATERIAL OF CONSTRUCTION	(INCLUDE STRUC	TURAL SYSTEMS	)	The state of the s
Floors are supported with	wooden ricor j	oists and wal	Is are brick load b	earing. The facad

Foundations are probably of brick.

SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE The building is rectangular, on a corner lot, and measures 30' x 75'. It is four stories high and has four bays.

EXTERIOR FEATURES OF NOTE

1001 D Street is four bays wide and four stories tall on a corner lot. facace on D Street is composed of a metal and glass show window on the west (left) and a wood and glass show window on the east. Both doorways are wood and glass, and are centere on the facade. A molded metal and wood cornice extends the width of (see attached)

INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)

The first floor is divided into two stores. On the corner is a Fotomat store; a small squ space with a counter and small office. The liquor store is rectangular with a narrow exte sion running just north of the Fotomat's back wall. It is lined with shelves on all walls a commercial refrigerator at the north wall and a painted pressed metal ceiling. (see attac MAJOR ALTERATIONS AND ADDITIONS WITH DATES

Building Permits cited are as follows: (see attached)

PRESENT CONDITION AND USE Upper floors of the building are unused and in an unknown condition on the interior. The exterior suffers from common deterioration due to age and neglect. (see attached)

OTHER INFORMATION AS APPROPRIATE

See also DC-493 (SQUARE 348) for additional information.

SOURCES OF INFORMATION (INCLUOE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)
District of Columbia Recorder of Deeds; District of Columbia Tax Records, General Assessme and Building Permits, National Archives; Baist's Atlas of Washington, Martin Luther King Library, Washingtoniana Room, Washington, D.C.

COMPILER, AFFILIATION W.F. Hunter, Pennsylvania Avenue Development Corporation DATE

1001 D Street(Commercial Bldg)
(Carpel's Liquor Store; Fotomat)
HABS No. D.C.- 488
Page 2.

Date of Construction (cont'd)

Stylistically, the federal style of 1001 D Street appears in Washington during the first half of the 19th Century, commercializing the domestic Federal style seen in residences elsewhere in the city. A photograph in the collection of the PADC shows the north side of D Street between Tenth and Eleventh Street about 1888, and the building before the addition of the fourth story.

Tax Records show a marked increas in improvement values between 1844 and 1853 (1844-10t \$2262 improvements \$1900; 1853- Lot \$2261 improvements \$4500). The improvement value of \$4500 is entered in red ink, indicating construction.

# Exterior Features of Note (cont'd)

the building above the show windows.

Windows on the upper three floors have simple rectangular stone lintels and sills. Windows themselves have been covered with plywood.

The entablature consists of a cornice with modillions in the bed molding and a very narrow frieze.

The Tenth Street facade windows are identical to those on D Street. The add ition of the fourth floor is seen here to only include the front (south) portion of the building, with a tall parapet wall extending along the Tenth Street facade. Behind this is the hipped roof of the original building. Above the second story windows is a faded sign of the Walter B. Williams, Auctioneer, who occupied the building for many years.

## Interior Features of Note (cont'd)

Upper floors were not examined by this author due to health and lighting problems.

## Major Alterations and Additions With Dates (cont'd)

8/5/81 #274 - build bay window on D Street.

1/20/89 #980 - alter east front show window.

2/23/94 #1144 - build show window.

12/13/06#2000 - remove west show window and build new.

3/6/08 #2588 - build show window with prism glass.

5/1/13 #4007 - shore up balconey.

8/30/14 #1440 - remove window, cut door, 8'4" x 9'0" with lintel and relieving arch; cut wall and replace window in rear sidewall, Tenth Street.

1/7/24 #5643 - remove and replace same window; use iron beam in center column.

10/25/32#158490- provide floor covering in present elevator shaft.

8/30/45 #279854- Architect Eberhard; construct new show window.

(Note: the fourth floor addition is not documented with a building permit).

### Present Condition and Use (cont'd)

The intersection of the cornice above the show windows and the facade wall is seriously deteriorated, causing the cornice to sag significantly. The four courses above the cornice show signs of water damage with portions of brick and mortar missing. There are various areas on the facade where bricks have been loosened and stained.